Top Ten Major Nonconformities



10.2.3	Problem solving
10.2.1	Nonconformity and Correction Action
8.3.5.2	Manufacturing process design output
8.5.1.1	Control plan
7.1.5.1.1	Measurement systems analysis
6.1.2.3	Contingency plans
8.5.1	Control of Production and Service Provision
8.5.1.5	Total productive maintenance
9.1.1.1	Monitoring & measurement of manufacturing processes
7.1.5.2.1	Calibration/verification records

share of a top 10 clause in the total volume of major nonconformities

source of data: IATF
www.iatfglobaloversight.org